




P TRAPS



	<b>75</b>	<b>100</b>	<b>150</b>	<b>200</b>	<b>250</b>	<b>300</b>	<b>350</b>	<b>375</b>	<b>400</b>	<b>450</b>	<b>500</b>	<b>600</b>
<b>A</b>	102	108	108	152	152	152	203	203	203	203	203	203
<b>B</b>	203	241	330	428	491	575	710	747	791	875	966	1123



All dimensions are in millimeter